


210634


ALTERNATOR

TECHNICAL INFORMATION

As a consequence of the engine modifications made by Mercedes for SMART vehicles, the manufacturer Valeo decided to remove the fixing bushings because of variants that could not be respected in the supply. As our article 210634 is original Valeo article, it is without fixing bushings in the package.



Currently, as per the excerpt from the vehicle manufacturer's catalog below, given the variants of the vehicle applications, the fixing bushings must be purchased separately as Kit 214500.



500	A 132 150 01 16	LINK PORTANTE A 006 151 90 01 Sostituito da: A 132 150 02 16 [414] LA VECCHIA PARTE NON DEVE PIÙ INSTALLARE
500	A 132 150 02 16	GUARDARE IL LINER A 006 151 90 01